General Remodel Notes: - Demo & replace with similar flooring throughout (Existing: Laminate and carpet) - Patch and paint walls; replace base as needed; replace ceiling tile as needed HARTER SCHOOL FLOOR PLAN - coordinate paint color with existing PWD "standard white" - spec durable flooring (3-5 years) with easy maintenance care Renovate orox. 1 - ADA compliance at entry; ADA on SW corridors (see plan) L'emo existing existing room kitchen equipment into and 'eplace with new ADA BR **Existing Data Rack to** Remove all counters, cabinets and sink w/ new remain. It can fixtures, and cap entry accommodate lines additional switch and equipment. Consider enclosing for noise with 126 sq.ft. 124 sq.ft. appropriate cooling. 100 sq.ft. 192 sq.ft. Staff 206 sq.ft. 305 sq.ft Computer Rm Lounge (up to 15 machines) with ADA compliance JANITOR CLOSET 120 sq.ft. 241 sq.ft. STORAGE 58 sq.ft. SERVER ROOM 121 sq.ft. 126 sq.ft. 415 sq.ft. 260 sq.ft. Conference 125 sq.ft. 322 sq.ft. KITCHEN 121 sq.ft. Conference Rm 146 sq.ft. RmConference Rm 298 sq.ft. Receptionist Office Install transaction window RECEPTION FILES 123 sq.ft. 248 sq.ft. 88 sq.ft. 546 sq.ft. Hallway 142 sq.ft. 130 sq.ft. 130 sq.ft. 130 sq.ft. 128 sq.ft. Add access control to 128 sq.ft. 128 sq.ft. 128 sq.ft. 130 sq.ft. door controlled by receptionist room TER SCHOOL 2013 Demo all bathroom Areas to meet ADA design standards. fixtures/particians & - Install ADA compliant front entry doors with card access and ADA Button. replace with new. - Install ADA compliant doors for highlighted rooms. Maintain same layout - Adjust hallway thresholds to meet ADA widths in hallway. No airflow to rooms making it difficult to use as office space; previously used as storage

NCS Exterior Improvements

General Exterior Note:

- Prep and repaint exterior siding and doors

Cut and replace asphalt with ADA compliant ramp

Demo existing bed and entry; retain blocks to use on west side. Replace with Retain building asphalt and add retaining exterior sign frame, wall with new railing but remove existing insert Freight Area: - Remove and replace rail - "Re-grout" broken areas of landing pad - Install protective end cap/channel iron on delivery side - Install new iron posts 78289 Confederated Way Ramp Options: - Pricing to demo and install new stairs with landings for each door - New sheathing and deck replacement

Google

Beds:

- -Clear and grub around trees with selective demo of smaller trees.
- Import clean fill for the north bed and infill with 3/4" (intended use will be seating area)

Retaining wall

-Infill missing areas with scavenged blocks from the north side; replace remaining with matching block